

Facility Audit Summary

Date of Audit: Feb 16,2011

1 to 5 year Projected Needs

School	Growth Potential	Current ADM	Capacity Opt.	General Maintenance Roofing	Trade Cost	Electrical Lighting	Trade Cost	Technology	Trade Cost	HVAC	Trade Cost
Central Elem.	Slow	309	414	Roof systems are in fair condition. The BUR roof system over the kitchen needs repair.	23,000	Some of the emerg. lighting needs replaced	5,000	Wireless school Video Streaming Smart Technology Standardization Infrastructure upgrade		Balance Vent Fans in computer room Add heaters to heat pumps in gym Update hvac equipment that feed computer rooms down stairs Upgrade from Barber / Coleman to Allerton controls	750 1,000 2,500 70,000
				Information Photos			Information Photos			Information	Information
Total 1 to 5 year cost					23,000		5,000		80,000		74,250

5 to 10 year Projected Needs

Target Capacity	New Building Needed	Construction Cost	Target Time Line	Additional Space Needed	Construction Cost
600	Classroom wing	1,680,000		E.C./ Music/ Art/ Nurse station/ Work areas/ Computer Lab	1,260,000
	Main Building shingles	150,000			
Total 5 to 10 year cost		1,830,000			1,260,000

