

# Facility Audit Summary

Date of Audit: Feb 17, 2011

## 1 to 5 year Projected Needs

School	Growth Potential	Current ADM	Capacity Opt.	General Maintenance Roofing	Trade Cost	Electrical Lighting	Trade Cost	Technology	Trade Cost	HVAC	Trade Cost	Plumbing
East Iredell Elem	Slow	653	880	Roof systems are brand new (No problems at this time)	0	Gym lighting needs upgrade Gym power panels	10,000 5,000	Wireless school Video Streaming Smart Technology Standardization Infrastructure upgrade Enhance cell service in school	0 100,000 75,000 20,000	New gas pack units on fith grade building Upgrade kitchen and dining gaspack	45,000 25,000	Need upgrade in remaining bathrooms and kitchen and Gym
				<a href="#">Information Photos</a>			<a href="#">Information Photos</a>			<a href="#">Information</a>	<a href="#">Information</a>	
<b>Total 1 to 5 year cost</b>					0		15,000		195,000		70,000	

## 5 to 10 year Projected Needs

Target Capacity	New Building Needed	Constructi Cost	Target Time Line	Additional Space Needed	Construction Cost	Other Needs
880	None			Gym		None
<b>Total Estimated</b>		0		0	0	0
<b>Total 5 to 10 year cost</b>		0		0	0	



