

Facility Audit Summary

Date of Audit: Feb 24,2011

1 to 5 year Projected Needs

<i>School</i>	<i>Growth Potential</i>	<i>Current ADM</i>	<i>Capacity Opt.</i>	<i>General Maintenance Roofing</i>	<i>Trade Cost</i>	<i>Electrical Lighting</i>	<i>Trade Cost</i>	<i>Technology</i>	<i>Trade Cost</i>	<i>HVAC</i>	<i>Trade Cost</i>
Sharon Elem.	Slow	300	399	Medium Repairs/ replacement	0	OK	0	Wireless school	0	Balance	25,000
								Video Streaming	75,000	Vent Fans	2,500
				Metal roof systems NEW	0			Smart Technology	100,000	Need new ac	
				TPO roof system NEW	0			Standardization		units in data	
				Cooley roof systems BAD				Infrastructure		rooms	25,000
				B-Old Section	142,000			upgrade	90,000	Need new	
School Interview Audit				Auxiliary Building-shin- gles	12,000					furnaces in gym	15,000
										Upgrade gym	
										controls from	
										time clock to	
Google Site Map										Allerton	8,000
				Information		Information		Information		Information	
				Photos							
Total 1 to 5 year cost					154,000		0		265,000		75,500

5 to 10 year Projected Needs

<i>Target Capacity</i>	<i>New Building Needed</i>	<i>Construction Cost</i>	<i>Target Time Line</i>	<i>Additional Space Needed</i>	<i>Construction Cost</i>
600	Classroom wing	650,000		Expand Cafeteria	400,000
	Old Gym Renovation	100,000			
Total 5 to 10 year cost					
		750,000			400,000

