

**Facility Audit Summary**

Date of Audit: Feb 24,2011

**1 to 5 year Projected Needs**

School	Growth Potential	Current ADM	Capacity Opt.	General Maintenance Roofing	Trade Cost	Electrical	Trade Cost	Technology	Trade Cost	HVAC	Trade Cost	Plumbing
<b>Brawley Middle</b>	<b>Medium</b>	<b>732</b>	<b>984</b>	Upgrade guttering Repair and / or replace roofing	10,000 50,000	Upgrade power panel in gym [this was done summer of 2011]	2,500	Infrastructure upgrade	100,000	Balancing upgrade of equipment and controls	150,000	Need Fixture upgrade in older buildings Need water coolers in entire school
				A-Gym shingles	21,000			Wireless school	0			
				C&D- 8thGrade wing old capsheet	94,000			Smart Technology	150,000			
				B-Gym old BUR	31,000							
				Multi-Purpose building shingle roof	16,000							
<a href="#">School Interview Audit</a>												
<a href="#">Google Site Map</a>												
				<a href="#">Information Photos</a>		<a href="#">Information Photos</a>		<a href="#">Information</a>		<a href="#">Information</a>		<a href="#">Information</a>
<b>Total 1 to 5 year cost</b>					222,000		2,500		250,000		150,000	

**5 to 10 year Projected Needs**

Target Capacity	New Building Needed	Construction Cost	Target Time Line	Additional Space Needed	Construction Cost	Other Needs
984	Redistrict or build New Middle in South	24,000,000		Storage	0	
<b>Total 5 to 10 year cost</b>		24,000,000			0	



