

Facility Audit Summary

Date of Audit: Feb 17, 2011

1 to 5 year Projected Needs

School	Growth Potential	Current ADM	Capacity Opt.	General Maintenance Roofing	Trade Cost	Electrical Lighting	Trade Cost	Technology	Trade Cost	HVAC	Trade Cost	Plumbing
East Iredell Middle	Slow	528	720	Metal roof system GOOD Few leaks reported		Lighting is T12 and could be upgraded to save energy.	150,000	Wireless school Video Streaming Smart Technology Standardization Infrastructure upgrade	125,000 100,000	Controls upgrade old Johnson to Allerton Install ac units in all computer labs	120,000 25,000	Renovate baths for E.C. Replace old Fixtures need low flow
				Information Photos			Information Photos	Information		Information		Information
Total 1 to 5 year cost					0		150,000		225,000		145,000	

5 to 10 year Projected Needs

Target Capacity	New Building Needed	Construct Cost	Target Time Line	Additional Space Needed	Construction Cost	Other Needs
720	Auxiliary space / Storage Concessions/ Baths Dressing	275,000		Expand & upgrade Cafeteria capacity	500,000	Storage
		275,000			500,000	0
Total 5 to 10 year cost		550,000			#####	

