

Facility Audit Summary

Date of Audit: May 1, 2011

1 to 5 year Projected Needs

School	Growth Potential	Current ADM	Capacity Opt.	General Maintenance Roofing	Trade Cost	Electrical Lighting	Trade Cost	Technology Communications	Trade Cost	HVAC	Trade Cost	Plumbing
Woodland Hts. Elem.	Medium	921	798	Metal roof systems GOOD (Minor leaks) TPO roof system over dinning room,kitchen area & gym storage rooms. GOOD (Minor leaks)	0	Power is ok	0	Wireless school Video Streaming Smart Technology Standardization Infrastructure upgrade	0	Balance equipment	25,000	Need sink faucets in gang Restrooms.
School Interview Audit				TPO roof system over Media Center. GOOD	0			Intercom Integrated	30,000			
Google Site Map				Information Photos		Information Photos		Information		Information		Information
Total 1 to 5 year cost					0		0		255,000		25,000	

5 to 10 year Projected Needs

Target Capacity	New Building Needed	Constructi Cost	Target Time Line	Additional Space Needed	Construction Cost	Other Needs
900	Classroom wing or New Elementary / Intermediate on site or at other site	See other sites				Expand Cafeteria
	Redistricting to fill Lakenorman Elem.	See LNES				
Total 5 to 10 year cost						

